

Inspection Report

Report No.: XYFA-140907
 Supplier : XY-GLOBAL

Inspection Date: 9th Oct., 2014
 Inspector: LEO

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYFA-140907 Item No. XY21ZC064 | Inspection Result: PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY21ZC064 | 6000pcs | 7% inspection | 0pcs | No failure | 6000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|---|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Inspection report: |

