

Inspection Report

Report No.: XYSL-140607
 Supplier : XY-GLOBAL

Inspection Date: 5th Jul, 2014
 Inspector: Leo



Inspection only for: PO . XYSL-140607 Item No. XY11WD031	Inspection Result: PASS
---	-----------------------------------



Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD031	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
--	--

<p>1. Packing</p> 	<p>2. Product</p> 
---	---

<p>3. Product</p> 	<p>4 Product</p> 
---	--

<p>5. Product:</p>	<p>6. The test report</p>
--------------------	---------------------------

