

Inspection Report

Report No.: XYGA-150320
 Supplier : XY-GLOBAL

Inspection Date: 23th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140320 Item No. XY21ZC057	Inspection Result: PASS
----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC057	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

