

**Inspection Report**

Report No.: XYBA-141129  
Supplier : XY-GLOBAL






Inspection Date: 26<sup>th</sup> Dec-, 2014  
Inspector:LEO

Inspection only for: PO . XYBA-141129    Item No. XY21ZC046	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC046	3000Pcs	7% inspection	0pcs	No failure	3000Pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

