

Inspection Report

Report No.: XYLA-150412
 Supplier : XY-GLOBAL







Inspection Date: 18th May, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150412 Item No. XY31PC022	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC022	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. report</p>



High qualified surface treatment can make your parts perfect !!!

