

**Inspection Report**

Report No.: XYAN-150420  
 Supplier : XY-GLOBAL

Inspection Date: 22<sup>th</sup> May-, 2015  
 Inspector: LEO

Inspection only for: PO . XYAN-150420    Item No. XY21ZC086	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC086	12000pcs	7% inspection	0pcs	No failure	12000pcs

**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:



Safety is our serious job for our worker and engineer team

