

Inspection Report

Report No.: XYN-140606
 Supplier : XY-GLOBAL









Inspection Date: 1st July, 2014
 Inspector: Leo

Inspection only for: PO . XYN-140606 Item No.103546	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
103546	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product::
	
5. Product:	6. Report:

