

Inspection Report







Report No.: XYSL-130513
 Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130513 Item No. XY11SL007	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL007	6000PCS	5% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

Company Name	Shanghai Luchuan Precision Machinery Co., Ltd. 10000000000000000000 OEM Precision Machining Service Provider
Material	ADC12 A380 Aluminum
Surface	Polished / Anodized
Material Properties	High precision, high strength, good surface finish
Process	CNC Machining
Surface Treatment	CNC Machining, Polishing, Anodizing, CNC Grinding
Quality Control	ISO9001, 100% Inspection, gague, High precision, high strength, good surface finish
Accuracy	±0.01mm
Lead Time	T / T 50% Advance Payment, T / T 50% Balance
Minimum Order	1000 Pieces
Lead Time	20-25 Days
Quality Control	ISO9001, 100% Inspection
1.Name: OEM Precision Machining Service Provider	
2.Process: CNC Machining	
3.Material: ADC12 A380 Aluminum	
4.Surface: Polished / Anodized	
5.Tolerance: 0.01 +/- mm	
6. Quality: 100% Inspection	
7.Specification: OEM Precision Machining Service Provider	
8. Lead Time: 20-25 Days	
9. Surface Treatment: Polished / Anodized / Accessoried	
10. Quality Control: ISO9001, 100% Inspection	
11. Certification: ISO 9001	
Company Name	
1. 10 Years Experience	
2. High Precision Machining	
3. All kinds of surface finishment available	
4. High precision, high strength, good surface finish	
5. ISO9001, 100% Inspection	
6. Lead Time	
7. Surface Treatment	
Company Name	
100% Inspection	
Surface Treatment: Polished / Anodized / Accessoried	
Quality Control: ISO9001, 100% Inspection	
Certification: ISO9001	
Lead Time: 20-25 Days	
Company Name OEM	