

Inspection Report

Report No.: XYDA-140504
 Supplier : XY-GLOBAL

Inspection Date: 1th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140504 Item No.1493768	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1493768	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

பெயர்	பெயர் / கிடைக்கக்கூடிய பெயர்
பெயர்	OEM பெயர் / கிடைக்கக்கூடிய பெயர்
பெயர்	ADC12 A380
பெயர்	பெயர்
பெயர்	பெயர்
பெயர்	CNC
பெயர்	gague
பெயர்	+/- 0.01MM
பெயர்	T / T 50
பெயர்	100
பெயர்	ISO 9001
பெயர்	OEM
பெயர்	1. 10
பெயர்	2.
பெயர்	3. kinds
பெயர்	4.
பெயர்	5.
பெயர்	6.
பெயர்	7.
பெயர்	ISO9001
பெயர்	OEM