

Inspection Report

Report No.: XYJ-1308025

Inspection Date: 19th Sep-, 2013

Supplier : XY-GLOBAL

Inspector:LEO

Inspection only for: PO . XYJ-130825 Item No.1401523	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1401523	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

