

Inspection Report

Report No.: XYI-140307
 Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
 Inspector: Leo

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYI-140307 Item No.140207 | Inspection Result: PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 140207 | 30000PCS | 1% inspection | 0pcs | No failure | 30000pcs |

| |
|--|
| Appearance Inspection : No failure. |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|---|
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Product: |
|  |  |
| 7. Product: | 8. Report: |

