

Inspection Report

Report No.: XYSL-130525
 Supplier : XY-GLOBAL

Inspection Date: 27th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130525 Item No. XY11SL015	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL015	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

