

**Inspection Report**

**Report No.:** XYN-140625  
**Supplier :** XY-GLOBAL

**Inspection Date:** 19<sup>th</sup> July, 2014  
**Inspector:** Leo

|  |                                   |
|--|-----------------------------------|
| Inspection only for:<br>PO . XYN-140625 Item No.357091 | <b>Inspection Result:</b><br>PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 357091      | 25000PCS      | 1% inspection | 0pcs         | No failure          | 25000pcs        |

|  |
|--|
| <b>Appearance Inspection :</b><br>No failure.  |
| <b>Dimension Inspection:</b><br>No failure , below measurement report for reference. |
| <b>Assembly Test:</b><br>No failure  |
| <b>Inspection Summary</b><br>The inspection sample plan is 100% inspection.          |

|   |  |
|---|--|
| Digital photo records :   |  |
|  |  |
| 1. Packing  | 2. Product   |
|  |  |
| 3. Product  | 4 Product  |
|  |  |
| 5. Product:   | 6. Report:   |

