

Inspection Report

Report No.: XYSL-150614
 Supplier : XY-GLOBAL

Inspection Date: 18th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150614 Item No. XY31XL012	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL012	9800PCS	1% inspection	0pcs	No failure	9800pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Safety is our serious job for our worker and engineer team

