

Inspection Report

Report No.: XYND-140512
Supplier : XY-GLOBAL

Inspection Date: 5th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYND-140512 Item No.30013467	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
30013467	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

