

Inspection Report

Report No.: XYKB-140505
 Supplier : XY-GLOBAL

Inspection Date: 2nd Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140505 Item No. XY72YM002	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM002	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



5. Product: 6. Dimensions report:

Company Name	Company Name OEM Product Name Material
Material	Material ADC12 A380
Surface	Surface
Process	Process
Dimension	CNC Dimension
Quality	Quality gague
Tolerance	Tolerance +/- 0.01MM
Lead Time	Lead Time T / T 50
Specification	Specification OEM
Accessories	Accessories
ISO	ISO 9001
Other	Other
1.Name:	1.Name: Company Name OEM Product Name Material
2.Process:	2.Process: Process
3.Material:	3.Material: Material ADC12 A380
4.Surface	4.Surface Surface
5.Tolerance:	5.Tolerance: 0.01 +/- 0.01MM
6. Quality:	6. Quality: 100
7.Specification:	7.Specification: OEM
8.	8. 30-25
9.	9. accessories
10.	10. AUSTRIAL
11.	11. ISO 9001
1.	1. 10
2.	2.
3.	3. kinds surface finishment available
4.	4.
5.	5.
6.	6.
7.	7.
8.	8.
9.	9.
10.	10. ISO9001
11.	11. OEM