

**Inspection Report**

**Report No.:** XYS-130802  
**Supplier :** XY-GLOBAL

**Inspection Date:**04<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYS-130802    Item No.1401030	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1401030	90000PCS	1% inspection	0pcs	No failure	90000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

