

Inspection Report

Report No.: XYN-131114
Supplier : XY-GLOBAL

Inspection Date: 4th Dec-, 2013
Inspector:KEN

Inspection only for: PO . XYN-131114 Item No.XY-MST-030	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-030	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

