

Inspection Report

Report No.: XYKB-140518
Supplier: XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140518 Item No. XY72YM014	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM014	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :																			
																			
1. Packing	2. Product																		
																			
3. Product	4 Product																		
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Product Name</td> <td>XY72YM014</td> <td>Product Type</td> <td>XY72YM014</td> <td>Inspection Date</td> <td>2014-6-12</td> </tr> <tr> <td>Order No.</td> <td>XYKB-140518</td> <td>Lot No.</td> <td>140518-001</td> <td>Inspector</td> <td>Leo</td> </tr> <tr> <td>Customer</td> <td>XY-GLOBAL</td> <td>Inspector</td> <td>Leo</td> <td>Inspection Status</td> <td>PASS</td> </tr> </table> <p>Inspection Summary: 100% inspection, 0 defects found.</p>	Product Name	XY72YM014	Product Type	XY72YM014	Inspection Date	2014-6-12	Order No.	XYKB-140518	Lot No.	140518-001	Inspector	Leo	Customer	XY-GLOBAL	Inspector	Leo	Inspection Status	PASS
Product Name	XY72YM014	Product Type	XY72YM014	Inspection Date	2014-6-12														
Order No.	XYKB-140518	Lot No.	140518-001	Inspector	Leo														
Customer	XY-GLOBAL	Inspector	Leo	Inspection Status	PASS														
5. Product:	6. Dimensions report:																		

