

Inspection Report

Report No.: XYDA-150304
Supplier : XY-GLOBAL

Inspection Date: 1th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150304 Item No. XY31CY024	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY024	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing	2. Product
	

3. Product	4 Product																
	 <p>深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Client Name</td> <td>Product Name</td> <td>Inspection Date</td> <td>Inspector</td> </tr> <tr> <td>XYDA-150304</td> <td>XY31CY024</td> <td>20150401</td> <td>Leo</td> </tr> <tr> <td>Product No.</td> <td>Lot No.</td> <td>Inspection Method</td> <td>Inspection Result</td> </tr> <tr> <td></td> <td></td> <td>100%</td> <td>PASS</td> </tr> </table>	Client Name	Product Name	Inspection Date	Inspector	XYDA-150304	XY31CY024	20150401	Leo	Product No.	Lot No.	Inspection Method	Inspection Result			100%	PASS
Client Name	Product Name	Inspection Date	Inspector														
XYDA-150304	XY31CY024	20150401	Leo														
Product No.	Lot No.	Inspection Method	Inspection Result														
		100%	PASS														
5. Product:	6. report																

