

Inspection Report


Report No.: XYAK-150416
 Supplier : XY-GLOBAL

Inspection Date: 20th May, 2015
 Inspector: Leo

Inspection only for: PO . XYAK-150416 Item No. XY31AL013	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL013	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Our sales team

