

Inspection Report

Report No.: XYDA-150320
Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150320 Item No. XY31CY037	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY037	66000PCS	1% inspection	0pcs	No failure	55000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co.,Ltd

Inspection	Product Name	Inspection Date	Inspector
品名: XYDA-150320	XYDA-150320	2015.04.15	Leo
规格: XYDA-150320	XYDA-150320	数量: 66000	物料: XY31CY037
数量: 66000	物料: XY31CY037	检验日期: 2015.04.15	检验员: Leo

检验标准: 根据客户提供的规格书及图纸进行检验, 如有不合格品, 请及时通知品管部处理。

检验结果: 合格

检验日期: 2015.04.15

检验员: Leo

检验地点: 仓库

检验设备: 游标卡尺, 千分尺

检验环境: 常温, 干燥

检验结论: 合格

检验报告编号: XYDA-150320-001

检验员: Leo

检验日期: 2015.04.15

5. Product:

6. report

