

Inspection Report

Report No.: XYWD-140705
 Supplier : XY-GLOBAL

Inspection Date: 28th July, 2014
 Inspector: Leo

Inspection only for: PO . XYWD-140705 Item No. XY31SY49	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY49	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
1. Packing	2. Product
3. Product	4 Product
5. Product:	6. report

