

□□□□□□□□ □□□□□□□□ □□□□ □□□□□□□□ □□□□

Inspection Report

Report No.: XYS-130630
Supplier : XY-GLOBAL

Inspection Date: 1th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130706 Item No.XY-1301483	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-131483	100PCS	5% inspection	0pcs	No failure	100pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Product Name	ADC12 A380 CNC Parts
Material	ADC12 A380
Surface	Polished
Tolerance	±0.01mm
Quality	100%
Specification	OEM
Lead Time	30-45 days
Payment	T/T
Minimum Order	1000 pieces
Factory Address	China
Product Description	CNC precision milled parts for various machinery. Material: ADC12 A380. Surface finish: polished. Tolerance: ±0.01mm. Quality: 100%. Specification: OEM. Lead time: 30-45 days. Payment: T/T. Minimum order: 1000 pieces. Factory address: China.
Product Name	ADC12 A380 CNC Parts
Material	ADC12 A380
Surface	Polished
Tolerance	±0.01mm
Quality	100%
Specification	OEM
Lead Time	30-45 days
Payment	T/T
Minimum Order	1000 pieces
Factory Address	China
Product Description	CNC precision milled parts for various machinery. Material: ADC12 A380. Surface finish: polished. Tolerance: ±0.01mm. Quality: 100%. Specification: OEM. Lead time: 30-45 days. Payment: T/T. Minimum order: 1000 pieces. Factory address: China.