

Inspection Report

Report No.: XYDA-140512
 Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140512 Item No.1400872	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400872	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Company Name	Shanghai Baohong Precision Machinery Co., Ltd. OEM parts manufacturer
Material	ADC12 A380
Surface	Polished
Process	CNC Machining
Tolerance	+/- 0.01MM
Quality	100%
Specification	OEM
Lead Time	30-25 days
Accessories	accessoried
Origin	AUSTRIAL
Certification	ISO 9001
Services	<ol style="list-style-type: none"> 1. 10 years experience 2. ISO 9001 certified 3. All kinds of surface finishment available 4. Competitive prices 5. Fast delivery 6. Good quality 7. OEM/ODM services
Contact	Shanghai Baohong Precision Machinery Co., Ltd.
Address	Shanghai, China
Phone	+86 21 5825 8888
Email	baohong@baohong.com.cn
Website	www.baohong.com.cn
Company	OEM