

**Inspection Report**

Report No.: XYSK-140602  
Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140602 Item No. XY31SY002	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY002	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :										
										
1. Packing	2. Product									
										
3. Product	4 Product									
	<p><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Customer: XY-GLOBAL</td> <td>Product Type: XY31SY002</td> <td>Inspection Date: 2014-07-02</td> </tr> <tr> <td>Part No: XY31SY002</td> <td>Lot No: XY31SY002</td> <td>Inspection Place: XY-GLOBAL</td> </tr> <tr> <td>Inspector: Leo</td> <td>Inspector: Leo</td> <td>Inspector: Leo</td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspector: Leo</p> <p>2014-07-02</p>	Customer: XY-GLOBAL	Product Type: XY31SY002	Inspection Date: 2014-07-02	Part No: XY31SY002	Lot No: XY31SY002	Inspection Place: XY-GLOBAL	Inspector: Leo	Inspector: Leo	Inspector: Leo
Customer: XY-GLOBAL	Product Type: XY31SY002	Inspection Date: 2014-07-02								
Part No: XY31SY002	Lot No: XY31SY002	Inspection Place: XY-GLOBAL								
Inspector: Leo	Inspector: Leo	Inspector: Leo								
5. Product:	6. report									

