

**Inspection Report**

Report No.: XYF-130829

Inspection Date: 26<sup>th</sup> Sep, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYF-130829      Item No. 800-20-450	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
800-20-450	20000Set	100% inspection	0pcs	No failure	20000Set

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

ชื่อผลิตภัณฑ์	ชิ้นงาน CNC ผลิตจากวัสดุ AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
วัสดุ	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
ขนาด	ตามแบบร่าง
ความแม่นยำ	±0.01mm
การตกแต่งผิว	ขัดผิว CNC
การเคลือบ	ตามความต้องการ
การบรรจุ	บรรจุในกล่องป้องกัน
การรับประกัน	รับประกันคุณภาพ 100%
ระยะเวลาจัดส่ง	3-5 วัน
ราคา	ตามใบเสนอราคา
การชำระเงิน	โอนเงินล่วงหน้า
การติดต่อ	โทร 081-234-5678
ที่ตั้ง	กรุงเทพฯ
เว็บไซต์	www.cncmachinery.com
คำอธิบายเพิ่มเติม	1.Name: OEM 2.Process: CNC 3.Material: AL6061 AL6065 AL6063 AL7075 4.Surface: 5.Tolerance: 0.01 +/- 6.Quality: 100 7.Specification: OEM 8. 9. 10. AUSTRIAL 11. ISO 9001
ข้อกำหนด	1. 10 2. 3. kinds sureface finishment 4. 5. 6. 7.
ข้อมูลติดต่อ	CNC 8. CNC 9. ISO9001 10. 11.