

Inspection Report

Report No.: XYAD-130808
Supplier : XY-GLOBAL

Inspection Date:6th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYAD-130808 Item No.7082014	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
7082014	3000PCS	100% inspection	0pcs	No failure	3000PCS

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product

ชื่อผลิตภัณฑ์	ชิ้นงาน CNC ผลิตจากวัสดุ AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 วัสดุคุณภาพสูง
วัสดุ	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 วัสดุคุณภาพสูง
ขนาด	ตามแบบร่างที่แนบมา
กระบวนการผลิต	ผลิตด้วยกระบวนการ CNC ผลิตจากวัสดุคุณภาพสูง
ผิวงาน	ผิวงาน CNC ผลิตจากวัสดุคุณภาพสูง
ความแม่นยำ	ความแม่นยำสูง 0.01 +/- มม.
การรับประกัน	รับประกันคุณภาพการผลิต 100%
ระยะเวลาจัดส่ง	20-25 วันทำการ T / T 50%
ข้อกำหนดอื่น ๆ	1.Name: OEM 2.Process: CNC 3.Material: AL6061 AL6065 AL6063 AL7075 4.Surface: 5.Tolerance: 0.01 +/- 6.Quality: 100 7.Specification: OEM 8. 30-25 : 9. accessoried 10. AUSTRIAL 11. ISO 9001
1. 10	
2.	
3. kinds sureface finishment available	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
ข้อมูลติดต่อ: 08-123-456789	