



Inspection Report

Report No.: XYF-130824
 Supplier : XY-GLOBAL

Inspection Date: 19th Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYF-130824 Item No. XY-MST-089	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-089	30000Set	100% inspection	Opcs	No failure	30000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. inspection reports

ชื่อผลิตภัณฑ์	ชิ้นงาน CNC ผลิตจากวัสดุ AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
วัสดุ	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
ขนาด	ตามแบบร่าง
คุณสมบัติ	ทนทาน แข็งแรง ใช้งานได้หลากหลาย
การประยุกต์ใช้	ชิ้นงาน CNC ผลิตจากวัสดุ AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
การรับประกัน	รับประกันคุณภาพ 100%
การจัดส่ง	จัดส่งทั่วประเทศ
การชำระเงิน	ชำระก่อนผลิต
การติดต่อ	โทร 02-123-4567
1.Name:	ชื่อผลิตภัณฑ์ OEM
2.Process:	CNC
3.Material:	AL6061 AL6065 AL6063 AL7075
4.Surface	ตามแบบร่าง
5.Tolerance:	0.01 +/-
6.Quality:	100%
7.Specification:	OEM
8.	ตามแบบร่าง
9.	ตามแบบร่าง
10.	AUSTRIAL
11.	ISO 9001
1.	ตามแบบร่าง
2.	ตามแบบร่าง
3.	ตามแบบร่าง
4.	ตามแบบร่าง
5.	ตามแบบร่าง
6.	ตามแบบร่าง
7.	ตามแบบร่าง
CNC	ตามแบบร่าง
CNC	ตามแบบร่าง
CNC	ตามแบบร่าง
CNC	ตามแบบร่าง
ตามแบบร่าง	ตามแบบร่าง