

Inspection Report

Report No.: XYGA-150321
 Supplier : XY-GLOBAL


Inspection Date: 23th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140321 Item No. XY21ZC058	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC058	10000pcs	7% inspection	Opes	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

