

□□□□ □□□□□□ CNC □□□□



Inspection Report

Report No.: XYK-130817  
 Supplier : XY-GLOBAL

Inspection Date:15<sup>th</sup> Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYK-130817      Item No.1305970	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1305970	3000PCS	3% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Product:

