

Inspection Report

Report No.: XYN-131107
Supplier : XY-GLOBAL

Inspection Date: 2th Dec-, 2013
Inspector:KEN

Inspection only for: PO . XYN-131107 Item No.XY-MST-023	<u>Inspection Result:</u> PASS
--	-----------------------------------


Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-023	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.


Digital photo records :




1. Packing




2. Product:




3. Product:



4. Product:



5. Product :



6. Product:

