

**Inspection Report**

Report No.: XYDA-150306  
Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup> Apr, 2015  
Inspector: Leo

Inspection only for: PO . XYDA-150306 Item No. XY31CY025	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY025	23000PCS	1% inspection	0pcs	No failure	23000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product
3. Product	4 Product
5. Product:	6. report

**XY-GLOBAL** 深圳市真朴电子科技有限公司  
XY Electronics Technology Co.,Ltd

XY Electronics Technology Co.,Ltd  
Product Name: XY31CY025  
Inspection Date: 2015.04.01

Inspector: Leo

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Report

Inspection Item: XY31CY025

Inspection Method: 100% inspection

Inspection Result: PASS

Inspection Date: 2015.04.01

Inspector: Leo

Inspection Report

Inspection Item: XY31CY025

Inspection Method: 100% inspection

Inspection Result: PASS

Inspection Date: 2015.04.01

Inspector: Leo

