

□□□□ □□□□□□□□ □□□□□□□□ A380 □□□□ □□□□ LED □□□□□□ □□□□

Inspection Report

Report No.: XYS-130717
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130717 Item No.XY-2524960	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-2524960	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Material	Material: Aluminum 6061-T6
Part Name	Part Name: OEM Part
Part Number	Part Number: ADC12 A380
Quantity	Quantity: 1000
Dimensions	Dimensions: 100x50x20mm
Surface Finish	Surface Finish: CNC Machined
Material Grade	Material Grade: CNC Machined Aluminum
Part Description	Part Description: Aluminum gague part
Lead Time	Lead Time: 2-3 weeks
Price	Price: \$10.00 per piece
Tolerance	Tolerance: +/- 0.01MM
Surface Treatment	Surface Treatment: T / T 50 or T / T 500
Quality Control	Quality Control: CNC Machined
Surface	Surface: 20-25 microns
Tolerance	Tolerance: 0.01 -/+ mm
Quality	Quality: 100% inspection
Specification	Specification: OEM Part
Lead Time	Lead Time: 30-25 days
Accessories	Accessories: accessoried parts
Material	Material: AUSTRIAL
Quality	Quality: ISO 9001
Surface	Surface: 10 microns
Lead Time	Lead Time: 2-3 weeks
Surface Finish	Surface Finish: available
Material	Material: Aluminum
Quantity	Quantity: 1000
Lead Time	Lead Time: 2-3 weeks
Surface	Surface: 20-25 microns
Tolerance	Tolerance: 0.01 -/+ mm
Quality	Quality: 100% inspection
Specification	Specification: ISO 9001
Lead Time	Lead Time: 30-25 days
Accessories	Accessories: accessoried parts
Material	Material: OEM Part