

**Inspection Report**

Report No.: XYD-140503  
 Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> Jun, 2014  
 Inspector: Leo

Inspection only for: PO . XYD-140503 Item No.XY-140223	<u>Inspection Result:</u> PASS
-----------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140223	50000PCS	1% inspection	0pcs	No failure	50000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:
	
7. Product:	8. Report:

