

Inspection Report

Report No.: XYK-131022
 Supplier : XY-GLOBAL

Inspection Date: 18th Nov-, 2013
 Inspector: ALEX

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYK-131022 Item No.XY-CT-D-085 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY-CT-D-085 | 6000PCS | 1% inspection | 0pcs | No failure | 6000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

