

Inspection Report

Report No.: XYN-140603
 Supplier : XY-GLOBAL

Inspection Date: 1st July, 2014
 Inspector: Leo

Inspection only for: PO . XYN-140603 Item No.202034	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
202034	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product::
	
5. Product:	6. Report:

