

Inspection Report

Report No.: XYF-130808
Supplier : XY-GLOBAL

Inspection Date: 2th Sep, 2013
Inspector: LEO

Inspection only for: PO . XYK-130808 Item No.200-40-130	Inspection Result: PASS
-----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-40-130	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

