



### Inspection Report

Report No.: XYK-131014  
Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> Nov-, 2013  
Inspector:ALEX

Inspection only for: PO . XYK-131014 Item No.XY-CT-D-046	<u>Inspection Result:</u> PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-046	20000PCS	0.1% inspection	0pcs	No failure	20000pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.






**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

