

**Inspection Report**

Report No.: XYK-140608  
 Supplier : XY-GLOBAL






Inspection Date:10<sup>th</sup> Sep-, 2014  
 Inspector:Alex

|   |                                   |
|---|-----------------------------------|
| Inspection only for:<br>PO . XYK-140608 | <u>Inspection Result:</u><br>PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 140608      | 1000PCS       | 3% inspection | 0pcs         | No failure          | 1000pcs         |

|  |
|--|
| <b>Appearance Inspection :</b><br>No failure,  |
| <b>Dimension Inspection:</b><br>No failure , below measurement report for reference. |
| <b>Assembly Test:</b><br>No failure  |
| <b>Inspection Summary</b><br>The inspection sample plan is 100% inspection.          |

Digital photo records :

|   |  |
|---|--|
|   |   |
| 1. Packing  | 2. Product:  |
|  |  |
| 3. Product:   | 4. Product:  |
|  |  |
| 5. Product :  | 6. Product:  |

