

**Inspection Report**





Report No.: XYSL-130519  
 Supplier : XY-GLOBAL

Inspection Date: 17<sup>th</sup> Jun, 2013  
 Inspector: Leo

|   |                                   |
|---|-----------------------------------|
| Inspection only for:<br>PO . XYSL-130519 Item No. XY11SL011 | Inspection Result:<br><b>PASS</b> |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY11SL011   | 6000PCS       | 5% inspection | 0pcs         | No failure          | 6000pcs         |

|  |
|--|
| <b>Appearance Inspection :</b>                       |
| No failure,  |
| <b>Dimension Inspection:</b>                         |
| No failure , below measurement report for reference. |
| <b>Assembly Test:</b>                                |
| No failure   |
| <b>Inspection Summary</b>                            |
| The inspection sample plan is 100% inspection.       |

|   |   |
|---|---|
| Digital photo records :   |   |
|   |   |
| 1. Packing  | 2. Product  |
|  |  |
| 3. Product  | 4 Product   |
|  |  |
| 5. Product.   | 6. The test report  |

