

Inspection Report







Report No.: XYFA-140902
 Supplier : XY-GLOBAL

Inspection Date: 2th Oct., 2014
 Inspector: LEO

Inspection only for: PO . XYBA-140902 Item No. XY21ZC059	Inspection Result: PASS
----------------------------------------------------------------	------------------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC059	3800pcs	7% inspection	0pcs	No failure	3800pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

