

**Inspection Report**

Report No.: XYDA-150303  
Supplier : XY-GLOBAL



Inspection Date: 1<sup>th</sup> Apr, 2015  
Inspector: Leo

Inspection only for: PO . XYDA-150303 Item No. XY31CY023	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY023	23000PCS	1% inspection	0pcs	No failure	23000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product
	

3. Product	4 Product
	 
5. Product:	6. report

