

Inspection Report

Report No.: XYKB-140510
 Supplier : XY-GLOBAL

Inspection Date: 6th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140510 Item No. XY72YM006	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM006	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :																															
																															
1. Packing	2. Product																														
																															
3. Product	4 Product																														
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Inspection Report No.</td> <td>XYKB-140510</td> <td>Product Name</td> <td>XY72YM006</td> <td>Inspection Date</td> <td>2014.6.6</td> </tr> <tr> <td>Order No.</td> <td>XYKB-140510</td> <td>Customer Name</td> <td>XY-GLOBAL</td> <td>Inspection Item</td> <td>外观尺寸</td> </tr> <tr> <td>Inspector</td> <td>Leo</td> <td>Inspector</td> <td>Leo</td> <td>Inspection Result</td> <td>PASS</td> </tr> </table> <p>Inspection Report No. XYKB-140510</p> <table border="1"> <thead> <tr> <th>Item No.</th> <th>Item Name</th> <th>Inspection Item</th> <th>Inspection Result</th> <th>Defect Count</th> <th>Defect Rate</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>外观尺寸</td> <td>外观尺寸</td> <td>合格</td> <td>0</td> <td>0%</td> </tr> </tbody> </table> <p>XY-GLOBAL (Group) Inspection Report</p>	Inspection Report No.	XYKB-140510	Product Name	XY72YM006	Inspection Date	2014.6.6	Order No.	XYKB-140510	Customer Name	XY-GLOBAL	Inspection Item	外观尺寸	Inspector	Leo	Inspector	Leo	Inspection Result	PASS	Item No.	Item Name	Inspection Item	Inspection Result	Defect Count	Defect Rate	1	外观尺寸	外观尺寸	合格	0	0%
Inspection Report No.	XYKB-140510	Product Name	XY72YM006	Inspection Date	2014.6.6																										
Order No.	XYKB-140510	Customer Name	XY-GLOBAL	Inspection Item	外观尺寸																										
Inspector	Leo	Inspector	Leo	Inspection Result	PASS																										
Item No.	Item Name	Inspection Item	Inspection Result	Defect Count	Defect Rate																										
1	外观尺寸	外观尺寸	合格	0	0%																										
5. Product:	6. Dimensions report:																														

