

Inspection Report







Report No.: XYN-140619
Supplier : XY-GLOBAL

Inspection Date: 14th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140619 Item No.209543	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
209543	9000PCS	1% inspection	0pcs	No failure	9000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

