

Inspection Report

Report No.: XYK-131027
Supplier : XY-GLOBAL

Inspection Date: 24th Nov-, 2013
Inspector:ALEX

Inspection only for: PO . XYK-131027 Item No.XY-CT-D-090	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-090	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

