

**Inspection Report**

Report No.: XYAN-150302-1  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup> Apr, 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150302-1    Item No. XY21ZC089	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC089	8000pcs	7% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

6. Inspection report:



Safety is our serious job for our worker and engineer team

