

**Inspection Report**



Report No.: XYL-150729  
 Supplier : XY-GLOBAL

Inspection Date: 14<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150729 Item No. XY11LM029	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM029	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :															
															
1. Packing	2. Product														
															
3. Product	4 Product														
	 <p><b>检查报告</b></p> <p>品名: XY11LM029              规格: 12000PCS              日期: 2015.09.14</p> <table border="1"> <thead> <tr> <th>品名</th> <th>规格</th> <th>数量</th> <th>单位</th> <th>检验员</th> <th>检验日期</th> <th>检验结果</th> </tr> </thead> <tbody> <tr> <td>XY11LM029</td> <td>12000PCS</td> <td>12000</td> <td>PCS</td> <td>Leo</td> <td>2015.09.14</td> <td>PASS</td> </tr> </tbody> </table>	品名	规格	数量	单位	检验员	检验日期	检验结果	XY11LM029	12000PCS	12000	PCS	Leo	2015.09.14	PASS
品名	规格	数量	单位	检验员	检验日期	检验结果									
XY11LM029	12000PCS	12000	PCS	Leo	2015.09.14	PASS									
5. Product:	6. Report:														



Safety is our serious job for our worker and engineer team

