

Inspection Report







Report No.: XYSL-150722
 Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2015
 Inspector: Leo

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYSL-150722 Item No. XY31XL042 | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31XL042 | 13000PCS | 1% inspection | 0pcs | No failure | 13000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. report |

Safety is our serious job for our worker and engineer team

