



### Inspection Report

Report No.: XYJ-131015  
Supplier : XY-GLOBAL

Inspection Date:9<sup>th</sup> Nov-, 2013  
Inspector:LEO

Inspection only for: PO . XYJ-131015    Item No.XY-CT-D-060	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-060	8000PCS	1% inspection	0pcs	No failure	8000pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

